

BROWNING BAR MAXIMA STEEL BASE MATTE BLACK

John Browning Would Be Proud to Have These on His Browning

Quality. Stability. Functionality. Words that describe the Warne Browning BAR Maxima Steel Base. The Warne Browning BAR Maxima Steel Base can be used in conjunction with Warne Maxima QD Rings allowing you to utilize the open sights and view over top of the bases while maintaining a normal shooting position. Modeled around the Weaver design. Strong and versatile mounting system. Bases offer full width recoil slot. Allows the recoil control keys to attain max bearing surface. Get the optics security you need and quit flushing money down the toilet on gear that doesn't work. Get yourself some Warne Browning BAR Maxima Steel Base.



Attributes

- Name: BROWNING BAR MAXIMA STEEL BASE MATTE BLACK
- Manufacturer: WARNE MFG. COMPANY
- Product no.: 947000690
- Mfr. No.: M996M
- Color: Matte Black
- Elevation: 0 MOA
- Make: Browning
- Material: Steel
- Model: BAR
- Number of Bases: 1-Piece
- Style: Weaver
- Delivery weight: 0.045kg
- Shipping height: 3mm
- Shipping width: 95mm
- Shipping length: 229mm
- UPC: 656813104260

Item details

Made in USA

Table of Contents

- [Startpage](#)
- [English: Safety Instruction Guide for Warne Browning BAR Maxima Steel Base](#)
- [Český: Návod k bezpečnému používání: Warne Browning BAR Maxima Steel Base](#)

Safety Instruction Guide for Warne Browning BAR Maxima Steel Base

Introduction

Thank you for choosing the Warne Browning BAR Maxima Steel Base. This guide provides essential safety instructions and usage guidelines to ensure the safe and effective use of this product. Please read this document carefully before installation and use.

General Safety Guidelines

- Ensure that the product is used only for its intended purpose.
- Always follow the installation instructions to avoid potential hazards.
- Regularly inspect the product for any signs of wear or damage.
- Keep this product out of reach of children and vulnerable individuals.
- Report any unsafe product experiences or accidents to the appropriate authorities.
- Stay informed about product recalls and safety updates via the EU's Safety Gate platform.

Specific Safety Precautions for Use

- **Mounting Safety:** Ensure that the base is securely mounted to avoid accidental dislodgment of optics.
- **Weight Limit:** Do not exceed the recommended weight limit for the optics mounted on the base.
- **Shooting Position:** Maintain a proper shooting position to ensure stability and safety during use.
- **Inspection:** Regularly check the base and rings for tightness and integrity before each use.
- **Environmental Conditions:** Avoid using the product in extreme weather conditions that may affect its performance.

Instructions for Installation and Usage

1. **Preparation:** Gather all necessary tools and ensure that you are working in a safe environment.
2. **Installation Steps:**
 - Remove any existing bases from the firearm.
 - Position the Warne Browning BAR Maxima Steel Base on the firearm according to the manufacturer's specifications.
 - Align the base with the mounting holes and ensure it is level.
 - Secure the base using the appropriate screws, ensuring they are tightened to the manufacturer's specifications.
3. **Mounting Optics:**
 - Once the base is securely installed, attach the Warne Maxima QD Rings.
 - Ensure that the optics are properly aligned and securely fastened within the rings.
4. **Final Check:**
 - Inspect the installation to ensure everything is secure and properly aligned before use.
 - Perform a test to ensure that the optics are stable and do not shift during handling.

Disposal Instructions

- Dispose of the product according to local regulations.
- If the product is no longer usable, consider recycling materials where possible.
- Do not dispose of the product in household waste unless permitted by local guidelines.

Contact Information for Further Support

For any inquiries or assistance regarding the Warne Browning BAR Maxima Steel Base, please refer to the manufacturer's contact information, which can typically be found on the product packaging or the manufacturer's website.

By following these guidelines, you can ensure the safe and effective use of your Warne Browning BAR Maxima Steel Base. Thank you for your attention to safety and for choosing our product.

Návod k bezpečnému používání: Warne Browning BAR Maxima Steel Base

Úvod

Děkujeme, že jste si zakoupili Warne Browning BAR Maxima Steel Base. Tento produkt je navržen tak, aby poskytoval bezpečnou a spolehlivou montáž pro vaše optické zařízení. Tento návod obsahuje důležité informace o bezpečnosti, používání a údržbě, které byste měli znát, abyste zajistili bezpečné a efektivní používání výrobku.

Obecné bezpečnostní pokyny

- Ujistěte se, že výrobek je používán pouze podle pokynů uvedených v tomto návodu.
- Dbejte na to, aby byl výrobek používán pouze osobami, které mají odpovídající znalosti a zkušenosti s montáží a používáním optických zařízení.
- Zkontrolujte, zda jsou všechny součásti výrobku v dobrém stavu před použitím.
- Udržujte výrobek mimo dosah dětí a zranitelných osob.
- Při používání výrobku dodržujte všechny místní zákony a předpisy.

Specifické bezpečnostní opatření pro použití

- Před instalací se ujistěte, že je zbraň vybitá a bezpečná.
- Při montáži se vyhněte použití nadměrné síly, abyste předešli poškození základny nebo zbraně.
- Pravidelně kontrolujte montážní systém a základnu na známky opotřebení nebo poškození.
- Nepoužívejte výrobek, pokud je poškozen nebo pokud se na něm nacházejí jakékoli viditelné vady.
- Při používání optických zařízení dodržujte pokyny výrobce optiky.

Pokyny pro instalaci a používání

1. Příprava na instalaci:

- Zkontrolujte, zda máte všechny potřebné nástroje a vybavení.
- Ujistěte se, že pracovní prostor je čistý a bezpečný.

2. Instalace základny:

- Umístěte základnu na vyhrazené místo na zbrani podle pokynů výrobce zbraně.
- Použijte šrouby a podložky dodané se základnou k upevnění základny k zbrani.
- Ujistěte se, že základna je pevně a bezpečně připevněna.

3. Montáž optiky:

- Připojte optické zařízení k základně pomocí Warne Maxima QD Rings.
- Zkontrolujte, zda je optika správně umístěna a zajištěna.

4. Kontrola před použitím:

- Před prvním použitím zkontrolujte, zda je vše správně namontováno a zajištěno.
- Otestujte stabilitu základny a optiky.

5. Údržba:

- Pravidelně kontrolujte základnu a upevnění na známky opotřebení.
- Čistěte základnu a optiku podle pokynů výrobce.

Pokyny pro likvidaci

- Při likvidaci výrobku dodržujte místní předpisy a zákony o odpadech.
- Nevyhazujte výrobek do běžného odpadu, pokud obsahuje nebezpečné materiály.
- Zvažte recyklaci materiálů, pokud je to možné.

Kontaktní informace pro další podporu

- Pro dotazy týkající se bezpečnosti a používání výrobku se obraťte na místní prodejce nebo výrobce.

Děkujeme za vaši pozornost a přejeme vám bezpečné a příjemné používání Warne Browning BAR Maxima Steel Base.